# SUBJECT INDEX

## **Brick masonry**

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

### Brittle fractures

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

### **Building codes**

Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

## **Building design**

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

### **Building**, office

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

### Buildings

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

### **Buildings**, office

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

Structure: U.S. Office Building in Moscow, Nicholas Carino, William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89 p16-34.

### Case reports

Investigative Studies of Ceiling Collapses, Fabian C. Hadipriono, CF Feb. 88 p44-51.

### Ceilings

Investigative Studies of Ceiling Collapses, Fabian C. Hadipriono, CF Feb. 88 p44-51.

### Chromates

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

# Collapse

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p.163-183.

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

Investigative Studies of Ceiling Collapses, Fabian C. Hadipriono, CF Feb. 88 p44-51.

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

# Collapse load

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

### Concrete deterioration

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

### Concrete, precast

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

### Concrete, reinforced

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

### Construction

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

### Construction costs

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

## Construction inspection

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

### Construction materials

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

### Construction site accidents

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

#### Corresion

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

### Cracking

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

### Cracks

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

### Design

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

### Engineering

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

#### Errors

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

## Evaluation

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

### Fallures

Collapse and Repair of Tall Concrete Silos with Fuspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

Search for the Cause of High-Speed-Channel Revetment Failures, Enzo Levi and Efrain del Risco, CF May 89 p125-136.

Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

### Failures, investigation

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

### Failures, investigations

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

## Federal government

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

Structure: U.S. Office Building in Moscow, Nicholas Carino, William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89 p16-34.

### Federal-state cooperation

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

## Field investigations

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

## Forensic engineering

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.

# Fracture strength

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

### Fractures

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

### Grain storage

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

### Human behavior

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

#### Human factors

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

### Hydraulics

Search for the Cause of High-Speed-Channel Revetment Failures, Enzo Levi and Efrain del Risco, CF May 89 p125-136.

### Inspection

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

### Interconnected systems

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

#### Joists

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

### Land fill

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

#### Leaching

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

### Lift-slab construction

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

### Liner

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

## Load resistant design factor

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

## Load shifting

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

## Maintenance

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

### Materials

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

### Materials failure

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

## Materials testing

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

#### Mediation

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

#### Models

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

## Optimal design

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

### Parapets

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

#### Peer review

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

## Performance evaluation

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

### Pipe design

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.

### Ponding

Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

## Professional practice

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

## Progressive failure

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

Investigative Studies of Ceiling Collapses, Fabian C. Hadipriono, CF Feb. 88 p44-51.

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

## Project management

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

## Quality assurance

- Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.
- Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.
- Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

## Quality control

- Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.
- Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.
- Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

### Rehabilitation

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

### Reinforcing steels

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

### Retrofitting

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

### Revetments

Search for the Cause of High-Speed-Channel Revetment Failures, Enzo Levi and Efrain del Risco, CF May 89 p125-136.

### Roof failure

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

### Roof failure

- Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.
- Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

## Salts effects

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

### Sheer

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

### Citos

- Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.
- Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

### Spowdrifts

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

### Spillways

Search for the Cause of High-Speed-Channel Revetment Failures, Enzo Levi and Efrain del Risco, CF May 89 p125-136.

### Sprinklers

Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

### Standards

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

#### Stee

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

## Steel pipes

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.

## Steel plates

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

#### Steel structures

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

### Strength

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

## Structural analysis

- Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.
- Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.
- Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.
- Structure: U.S. Office Building in Moscow, Nicholas Carino, William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89 p16-34.

### Structural design

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

## Structural engineering

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

## Structural stability

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

### Subsystem

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

### Suspended structures

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

#### Tanks

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

### Testing

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

## Timber construction

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

### Timbers

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

### Trusses

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

### U.S.S.R.

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15. Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone. CF Feb. 89 p57-75.

Structure: U.S. Office Building in Moscow, Nicholas Carino, William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89 p16-34.

### Volumetric strain

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

#### Walk

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

## Water pipelines

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.


### Welded tanks

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p.163-183.

### **Wood construction**

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.



# AUTHOR INDEX

Bell, Glenn R. Project Peer Review: Results of the Structural Failures II Conference, with Frank W. Kan and David R. Wright, CF Nov. 89, p218-225

Brander, Merle disc. (of Investigation of the Collapse of L'Ambiance Plaza, by Charles F. Scribner and Charles G. Culver, CF May 88, p58-79) with Richard Clark and John Frauenhoffer, CF Aug. 89, p203

Carino, Nicholas Structure: U.S. Office Building in Moscow, with William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89, n16-34

Carino, Nicholas J. see Wright, Richard N., CF Feb. 89, p2-15

see Santamarina, J. C., CF May 89, p78-86

Culver, Charles G.

see Scribner, Charles F., CF May 88, p58-79

see Levi, Enzo, CF May 89, p125-136

Derbalian, George K. see Moncarz, Piotr D., CF Aug. 87, p168-187

Dusenberry, Donald O.

disc. (of Investigative Studies of Ceiling Collapses, by Fabian C. Hadipriono, CF Feb. 88, p44-51), CF May 89, p140-141

Estenssoro, Luis F. Two Roof Failures Due to Water Ponding and Related Code Requirements, CF Aug. 89, p184-

Felsen, Michael D. Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, CF Nov. 89, p212-217

Frauenhoffer, John A. Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, CF May 89, p121-124

Gross, James G. Brick Masonry: U.S. Office Building in Moscow, with Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89, p35-56

see Carino, Nicholas, CF Feb. 89, p16-34 see Wright, Richard N., CF Feb. 89, p2-15

Gross, John L. Ashland Tank Collapse Investigation, with John H. Smith and Richard N. Wright, CF Aug. 89, p144-162

Gurfinket, German
Brittle Fracture and Collapse of Large GrainStorage Tank, CF Aug. 89, p163-183
Collapse and Repair of Tall Concrete Silos with
Suspended Steel Hopper, CF Nov. 89, p243-264
Restoring an Impaired Concrete Silo, CF May 89,
p87-99
disc. (of Inserting Concrete Silo, CF May 89,
disc.

disc. (of Investigation of the Collapse of L'Am-biance Plaza, by Charles F. Scribner and Charles G. Culver, CF May 88, p58-79), CF Aug. 89, p201-203

Hadipriono, Fabian C. Investigative Studies of Ceiling Collapses, CF Feb. 88, p44-51

disc: Donald O. Dusenberry, CF May 89,

p140-141 clo: CF May 89, p141-142

Hendrickson, Erik M.

see Carino, Nicholas, CF Feb. 89, p16-34

Hsieh, Hsin-Neng see Raghu, Dorairaja, CF May 89, p113-120

Kagan, Harvey A. Practical Quality-Controlled Construction, CF Aug. 89, p191-198

Kan, Frank W. see Bell, Glenn R., CF Nov. 89, p218-225

Levi, Enzo Search for the Cause of High-Speed-Channel Revetment Failures, with Efrain del Risco, CF May 89, p125-136

Mathey, Robert G. see Gross, James G., CF Feb. 89, p35-56

Mohsini, R. A.

Performance and Building: Problems of Evaluation, CF Nov. 89, p235-242

Moncarz, Plotr D. Failures of 108-Inch Steel Pipe Water Main, CF Aug. 87, p168-187 disc: Richard N. Wright, CF May 89, p139 clo: CF May 89, p140

O'Rourke, Michael J. disc. (of Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, by Rubin M. Zallen, CF May 88, p80-98), CF Nov. 89, p266-268

Raghu, Doralraja
Performance of Some Structures Constructed on
Chromium Ore Fills, with Hsin-Neng Hsieh, CF May 89, p113-120

Sansalone, Mary see Carino, Nicholas, CF Feb. 89, p16-34 see Wright, Richard N., CF Feb. 89, p2-15

Santamarina, J. C. Limitations in Decision Making and System Performance, with J. L. Chameau, CF May 89, p78-86

Scribner, Charles see Gross, James G., CF Feb. 89, p35-56

Scribner, Charles F.
Investigation of the Collapse of L'Ambiance Plaza,
CF May 88, p58-79

disc: German Gurfinkel, CF Aug. 89, p201-203 disc: Merle Brander, Richard Clark and John

disc: Merle Brander, Richard Clark and John Frauenhoffer, CF Aug. 89, p203 clo: CF Aug. 89, p203-209

Shyne, John C. see Moncarz, Piotr D., CF Aug. 87, p168-187

Simiu, Emil see Carino, Nicholas, CF Feb. 89, p16-34

Smith, John H. see Gross, John L., CF Aug. 89, p144-162

Stone, William C. see Carino, Nicholas, CF Feb. 89, p16-34 see Gross, James G., CF Feb. 89, p35-56 see Yokel, Felix Y., CF Feb. 89, p57-75

Stukhart, George Construction Materials Quality Management, CF May 89, p100-112

Wright, David R. see Bell, Glenn R., CF Nov. 89, p218-225

Wright, Richard N. Assessment: U.S. Office Building in Moscow, with

Assessment: O.S. Office Building in Moscow, with Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89, p2-15 disc. (of Failures of 108-Inch Steel Pipe Water Main, by Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87, p168-187), CF

May 89, p139
see Carino, Nicholas, CF Feb. 89, p16-34
see Gross, John L., CF Aug. 89, p144-162
see Yokel, Felix Y., CF Feb. 89, p57-75

Yokel, Felix Y. Progressive Collapse: U.S. Office Building in Moscow, with Richard N. Wright and William C. Stone, CF Feb. 89, p57-75 see Carino, Nicholas, CF Feb. 89, p16-34

Zallen, Rubin M.
Roof Collapse Under Snowdrift Loading and Snow
Drift Design Criteria, CF May 88, p80-98
disc: Michael J. O'Rourke, CF Nov. 89,
p266-268
clo: CF Nov. 89, p268

